

SURFACE MAINTENANCE

FY-04 BEST MANAGEMENT PRACTICES

- Total mulch applied to slopes to date: 43,870 yds³
 - Total silt fencing applied to date: 100 linear feet
 - Total amount of tackifier applied to exposed slopes to date: 1,400 gal.
 - Total amount of Soilfloc applied to exposed slopes to date: 33,400 gal.
 - Added three gallons of soilfloc directly into the retention basin
- 

SURFACE MAINTENANCE

FY-04 BEST MANAGEMENT PRACTICES

- Total amount of water pumped from storm water retention basin to date: 1,264,000 gallons
- Additional rip-rap channel placed to date: 300 ft
- Installed one 50 foot wide road crossing over the drainage course south of the greens area with two 24 inch HDPE pipes.

